



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

May 21, 2019

Ken Fleck, Manager of Geology and Environmental Affairs
Interwest Mining Company
P.O. Box 310
Huntington, Utah 84528

Subject: Conditional Approval for Revision to Hydrologic Section, PacifiCorp,
Cottonwood/Wilberg Mine, C/015/0019, Task ID#5926

Dear Mr. Fleck:

The above-referenced amendment is approved conditioned upon receipt of 2 clean copies prepared for incorporation. Please submit these copies by June 21, 2019. Once we receive these copies, final approval will be granted.

A stamped incorporated copy of the approved plans will also be returned to you at that time, for insertion into your copy of the Mining and Reclamation Plan.

If you have any questions, please call me at (801) 538-5350.

Sincerely,

Steve Christensen
Coal Program Manager

SKC/sqs
O:\015019.CWW\WG5926 HYDRO\CONDITIONALAPPROVAL.DOC



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Technical Analysis and Findings

Utah Coal Regulatory Program

PID: C0150019
TaskID: 5926
Mine Name: COTTONWOOD/ WILBERG
Title: REVISION TO HYDROLOGIC SECTION

Operation Plan

Hydrologic General

Analysis:

The amendment meets the State of Utah R645 requirements for General Hydrologic Information.

The amendment removes the annual report commitment within the Hydrologic Monitoring Program for the Cottonwood-Wilberg mine. The commitment to produce an annual report on the hydrology of East Mountain was intended to be fully removed by redline strikeout in the 'Reduction in Hydrologic Monitoring' Task #5770. However, one sentence at the end of the monitoring program was accidentally left in. This amendment appropriately cleans up the monitoring program by removing the last mention of the annual report commitment, thus making the monitoring program consistent throughout. This same error is also being cleaned up in the Deer Creek mine Hydrologic Monitoring Program under Task #5925.

kstorrar